

# Buffalo HT Fan has the solution




## Broken cast paddle wheel replaced in 2 days!!!

- A manufacturer of copier toner in the eastern United States was forced to reduce production when a cast alloy paddle wheel failed.
- A replacement wheel from the original manufacturer was a long lead item, and the customer could not wait.
- The customer contacted Buffalo HT Fan for help.
- Buffalo HT Fan Co. ASME certified welders built a complete replacement wheel in less than 48 hours. The fan wheel was then balanced to ISO G2.5 specs.
- The replacement wheel was completed on time, as promised. Even with the rush delivery, it was lower cost than a replacement from the original OEM.
- Buffalo HT Fan built a heavy duty, 100 % fabricated (NOT CAST) wheel at a very competitive price.

The reason many fan manufacturers offer wheels with cast spiders, and in some cases cast backplates, centerplates, and even partial blade sections is because they are **LESS COSTLY TO BUILD**.

In our experience, they are also less reliable. They are also very difficult to properly repair, if they are repairable at all.

©COPYRIGHT 2008 BUFFALO HT FAN CO. INC.



**For cost effective solutions to your fan problems, call us today. We can help.**

Buffalo HT Fan Company, Inc.

P.O. Box 1955, Buffalo, NY 14219-1955

Phone: (800) 657 9182

Fax: (800) 657 9435

E-mail: [sales@buffalohtfan.com](mailto:sales@buffalohtfan.com)

**Your best source for engineered OEM replacement fan equipment, fan repair & rebuilding, & dynamic balancing.**